



Quick Start Guide

**BULLSEYE
PRECISION
GAUGE PIEZO**




1

Install batteries, press power button and verify that the display lights up




2

Plumb the Piezo sensor into your vacuum system



3

Connect the threaded end of the sensor cable to the vacuum sensor



4

Verify that the readings make sense